




FUARO 100 C
(Английский ключ)



FUARO 100 CA
ключ-ключ



FUARO 100 CM
ключ-вертушка



Обозначение	Размеры, мм	
	A	B
100 CA 62 mm (26+10+26)	26	26
100 CA 65 mm (25+10+30)	25	30
100 CA 68 mm (26+10+32)	26	32
100 CA 70 mm (25+10+35)	25	35
100 CA 70 mm (30+10+30)	30	30
100 CA 75 mm (30+10+35)	30	35
100 CA 80 mm (30+10+40)	30	40
100 CA 80 mm (35+10+35)	35	35
100 CA 85 mm (35+10+40)	35	40
100 CA 90 mm (30+10+50)	30	50
100 CA 90 mm (35+10+45)	35	45
100 CA 90 mm (40+10+40)	40	40
100 CA 95 mm (30+10+55)	30	55
100 CA 95 mm (40+10+45)	40	45
100 CA 100 mm (45+10+45)	45	45
100 CA 105 mm (30+10+65)	30	65

Обозначение	Размеры, мм	
	A	B
100 CM 68 mm (26+10+32)	26	32
100 CM 70 mm (30+10+30)	30	30
100 CM 80 mm (30+10+40)	30	40
100 CM 80 mm (35+10+35)	35	35